

# WARNING (Clearances)

M55006

Rev. B

It is important that you check the clearances between the oil pump, crankshaft, connecting rods, and oil pan.

Make sure that the oil pick-up screen is not making contact with the oil pan.

Failure to insure proper clearances VOIDS any warranty of this product.

(Correct Intermediate Shaft)

A NEW INTERMEDIATE SHAFT with a PINNED STEEL SLEEVE MUST be used with this Oil Pump Application. DO NOT use a substitute.

If the STEEL SLEEVE is not used the driveshaft of the Oil Pump can be damaged, resulting in failure of the pump. Failure to follow this warning VOIDS any warranty of this product.

OVER

## Important Notice (Oil Pressure)

This Oil Pump is a High Volume, High Pressure Pump.

If a lower pressure is desired, remove the Colored High Pressure Spring and replace it with enclosed Non Colored Spring.